

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
1	BRS	L2	186	384/271	USPAT; EPO; JPO; DERWEN T	2003/04/04 11:40		
2	BRS	L1	306	384/275	USPAT; EPO; JPO; DERWEN T	2003/04/04 11:51		
3	BRS	L3	0	bushind same bearing same bronze	USPAT; EPO; JPO; DERWEN T	2003/04/04 11:52		
4	BRS	L4	632	bushing same bearing same bronze	USPAT; EPO; JPO; DERWEN T	2003/04/04 11:52		
5	BRS	L5	65	bushing same bearing same bronze and 384/\$.ccls.	USPAT; EPO; JPO; DERWEN T	2003/04/04 11:59		
6	BRS	L6	0	bushing same bearing same "nylon-coated" same steel and 384/\$.ccls.	USPAT; EPO; JPO; DERWEN T	2003/04/04 12:00		

	Err ors
1	0
2	0
3	0
4	0
5	0
6	0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Initiation
7	BRS	L7	0	"nylon-coated" same bushing	USPAT; EPO; JPO; DERWEN T	2003/04/04 12:00		n
8	BRS	L8	2	"nylon coated" same bushing	USPAT; EPO; JPO; DERWEN T	2003/04/04 12:01		
9	BRS	L9	4	steel same bushing same (coat or coating) with nylon	USPAT; EPO; JPO; DERWEN T	2003/04/04 12:02		

	Err ors
7	0
8	0
9	0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Condition
1	BRS	L1	99	301/36.2	USPAT; EPO; JPO; DERWEN T	2002/10/22 20:20		
2	BRS	L89	56	301/36.3	USPAT; EPO; JPO; DERWEN T	2002/10/22 20:45		
3	BRS	L129	361	301/36.1	USPAT; EPO; JPO; DERWEN T	2002/10/22 20:48		
4	BRS	L351	864	(independent or independently) same (rotatable or rotation) same wheel same bearing	USPAT; EPO; JPO; DERWEN T	2002/10/22 21:09		
5	BRS	L352	30	(independent or independently) same (rotatable or rotation) same wheel same bearing same bushing	USPAT; EPO; JPO; DERWEN T	2002/10/22 21:09		